

# Shamir Single Vision III As Worn™

## Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Color	Invisible Marking
Hard Resin	1.498	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Clear	15 III SV>>
Transitions®	1.5	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Gray & Brown	TR III SV>>
Transitions® XTRActive®	1.5	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Gray	X5 III SV>>
Polarized	1.498	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Gray & Brown	PZ III SV>>
Drivewear®	1.5	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Drivewear®	DW III SV>>
DLC™ (Trivex)	1.53	-14.00 to +6.75	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Clear	TX III SV>>
DLC™ (Trivex) Transitions®	1.53	-14.00 to +6.75	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Gray & Brown	TTX III SV>>
DLC™ (Trivex) Transitions® XTRActive™	1.53	-14.00 to +6.75	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Gray	TXX III SV>>
DLC™ (Trivex) Polarized	1.53	-14.00 to +6.75	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Gray & Brown	PTX III SV>>
1.56	1.56	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	Clear	56 III SV>>
Polycarbonate	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	Clear	PC III SV>>
Polycarbonate Transitions®	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	Gray & Brown	PT III SV>>

\* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®

# Shamir Single Vision III As Worn™

## Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Color	Invisible Marking
Polycarbonate Transitions® XTRActive™	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	Gray	PX III SV>>
Polycarbonate Polarized	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	Gray & Brown	PPZ III SV>>
Polycarbonate Drivewear®	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	Drivewear®	PW III SV>>
Superlite™ 1.6	1.6	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	Clear	16 III SV>>
Superlite™ 1.6 Transitions®	1.6	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	Gray & Brown	T6 III SV>>
Superlite™ 1.6 Transitions® XTRActive™	1.6	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	Gray	X6 III SV>>
Superlite™ 1.6 Polarized	1.6	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	Gray & Brown	PZ6 III SV>>
Superlite™ 1.67	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5, 11, 12.5	Clear	67 III SV>>
Superlite™ 1.67 Transitions®	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5, 11, 12.5	Gray & Brown	T67 III SV>>
Superlite™ 1.67 Transitions® XTRActive™	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5, 11, 12.5	Gray	X67 III SV>>
Superlite™ 1.67 Polarized	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5, 11, 12.5	Gray & Brown	PZ67 III SV>>
Superlite™ 1.74	1.74	-20.00 to +15.50	0.5, 1, 1.5, 2.5, 3.5, 4.75, 6, 7, 8, 9, 9.75, 10.5, 11.25, 12	Clear	74 III SV>>
Superlite™ 1.74 Transitions®	1.74	-20.00 to +15.50	0.5, 1, 1.5, 2.5, 3.5, 4.75, 6, 7, 8, 9, 9.75, 10.5, 11.25, 12	Gray & Brown	X74 III SV>>

\* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



ReCreating Perfect Vision®